Mr. Dee C. Hansen:

Following is the Commissioner's Report and brief breakdown of water on Pot Creek for 1976.

We went into the fall of 1975 with some water in storage. Crouse Reservoir was about 2/3 full, Calder upper was about 1/2 full and Calder lower was empty because of fish salvage.

We had about an average runoff in the spring of 1976. Calder upper and lower filled, but very little ran over the spillways of Calder lower or Crouse Reservoirs.

We had practically no moisture after the first of June.

Wildlife Resources received a total of 373.62 cfs. (Crouse Reservoir)

Calder received a total of 1,127.00 cfs.

Colorado received 188.70 cfs. and also the following:

Total 453.52 Acre Feet

All other rights satisfied: Siddoway

Bennion Searle Rasmussen

Submitted by: Udell Gardiner

MAR 15 19//

UPPER GAUGE

(State)

10/1/75	.10	10/17/75	.33
10/2/75	.10	10/18/75	.30
10/3/75	.11	10/19/75	.29
10/4/75	.11	10/20/75	.27
10/5/75	.11	10/21/75	.28
10/6/75	.11	10/22/75	.29
10/7/75	.15	10/23/75	.32
10/8/75	.31	10/24/75	.41
10/9/75	.26	10/25/75	.48
10/10/75	.22	10/26/75	.51
10/11/75	.21	10/27/75	.59
10/12/75	.21	10/28/75	.50
10/13/75	.49	10/29/75	.51
10/14/75	.43	10/30/75	.57
10/15/75	.40	10/31/75	.61
10/16/75	.38		

Total

UPPER GAUGE (State)

11/1/75	. 55	11/16/75	.40
11/2/75	.53	11/17/75	.39
11/3/75	.51	11/18/75	.36
11/4/75	.47	11/19/75	.38
11/5/75	.43	11/20/75	.39
11/6/75	.43	11/21/75	.31
11/7/75	.38	11/22/75	.27
11/8/75	.36	11/23/75	.26
11/9/75	.37	11/24/75	.25
11/10/75	.32	11/25/75	.24
11/11/75	.34	11/26/75	.22
11/12/75	.34	11/27/75	.21
11/13/75	.42	11/28/75	.20
11/14/75	.44	11/29/75	.19
11/15/75	.41	11/30/75	.18

Total

UPPER GAUGE (State)

12/1/75	10
12/2/75	.18
12/3/75	.17
12/4/75	.16
12/5/75	.16
12/6/75	.16
12/7/75	.16
	-16
12/8/75	.16
12/9/75	.16
12/10/75	.15
12/11/75	•
12/12/75	.14
12/13/75	.13
12/14/75	.12
12/15/75	.11
12/16/75	.10
/10//5	.05
Total	
	. 2 27

UPPER GAUGE (State)

3	3/12/76	.02
3	3/13/76	.04
3	3/14/76	.06
3	3/15/76	.08
3	3/16/76	.10
3	3/17/76	.12
3	3/18/76	.22
3	3/19/76	.22
3	3/20/76	.22
3	3/21/76	.22
3	3/22/76	.22
3	3/23/76	.38
3	3/24/76	.90
3	3/25/76	1.30
3	3/26/76	.53
3	3/27/76	.38
3	3/28/76	.30
3	3/29/76	.27
3	/30/76	.27
3	/31/76	.38

Total

UPPER GAUGE

State		Calder	
4/1/76	.58		
4/2/76	2.2		
4/3/76	4.2		
4/4/76	2.8		
4/5/76	1.0		
4/6/76	1.4		
4/7/76	1.7		
4/8/76	4.2		
4/9/76	5	4/9/76	10
4/10/76	5	4/10/76	131
4/11/76	5	4/11/76	108
4/12/76	5	4/12/76	87
4/13/76	5	4/13/76	114
4/14/76	5	4/14/76	104
4/15/76	5	4/15/76	30
4/16/76	5	4/16/76	17
4/17/76	5	4/17/76	12
4/18/76	5	4/18/76	9
4/19/76	5	4/19/76	7
4/20/76	5	4/20/76	6
4/21/76	5	4/21/76	13
4/22/76	5	4/22/76	15
4/23/76	5	4/23/76	28
4/24/76	5	4/24/76	26
4/25/76	5	4/25/76	27
4/26/76	5	4/26/76	17
4/27/76	5	4/27/76	15
4/28/76	, 5 ,	4/28/76	11
4/29/76	5	4/29/76	12
4/30/76	5	4/30/76	14
Total	128.08	Total	813.00

UPPER GAUGE

	<u>State</u>	Colorado	Calder
77 6	· 5	6	10
5/2/76	5	6	15
5/3/76	5	6	13
5/4/76	5	6	12
5/5/76	5	6	9
5 /6/ 76	5	6	9
5/7/76	5	6	16
5/8/76	5	6	14
5/9/76	5	6	14
5/10/76	5	6	13
5/11/76	5	6	13
5/12/76	5	6	11
5/13/76	5	6	9
5/14/76	5	6	9
5/15/76	.5	6	12
5/16/76	5	6	10
5/17/76	5	6	8
3/76	5	6	9
5/19/76	5	6	10
5/20/76	5	6	10
5/21/76	5	6	10
5/22/76	5	6	15
5/23/76	5	6	17
5/24/76	5	6	15
5 /25/76	5	6	וו
5/26/76	5	6	10
5/27/76	5	, 6	7
5/28/76	5	6	3
5/29/76	5	6	
5/30/76	5	5	
5/31/76	5	4.2	·
Total	155.0	183.2	314.0

	<u>State</u>				Co1	orado
6/1/76	5					3.1
6/2/76	5					1.8
6/3/76	5					.6
6/4/76	4.4					
6/5/76	4.0					
6/6/76	3.6					
6/7/76	2.9					
6/8/76	2.6					
6/9/76	1.9		•			
6/10/76	1.6					
6/11/76	1.7					
6/12/76	2.0					
6/13/76	1.8					
6/14/76	2.2					
6/15/76	2.1					
6/16/76	1.6					
6/17/76	1.7					
6/18/76	1.6					
6/19/76	1.2					
6/20/76	.90					
6/21/76	.72					
6/22/76	.81					
6/23/76	1.4					
6/24/76	.76					
6/25/76	.62					
6/26/76	.49					
6/27/76	. 41					
6/28/76	.41					
6/29/76	.41					
6/30/76	.36	•				
Total	59.19					5.5

(State)

7/1/76	.33
7/2/76	.36
7/3/76	.33
7/4/76	.27
7/5/76	.22
7/6/76	.16
7/7/76	.14
7/8/76	.12
7/9/76	.10
7/10/76	.08
7/11/76	.04
7/12/76	0
7/13/76	.06
7/14/76	.10
7/15/76	.03
Total	2.34

TOTAL UPPER GAUGE

10/2/75 9.3 11/2/75 .11 12/2/75 . 10/3/75 9.9 11/3/75 .10 12/3/75 .						
10/3/75 9.9 11/3/75 .10 12/3/75 . 10/4/75 10.0 11/4/75 .07 12/4/75 . 10/5/75 11.0 11/5/75 .08 10/6/75 11.0 11/6/75 .08 10/7/75 13.0 11/7/75 .07 10/8/75 12.0 11/8/75 .07 10/10/75 12.0 11/10/75 .07 10/11/75 12.0 11/11/75 .06 10/11/75 12.0 11/11/75 .06 10/11/75 13.0 11/12/75 .05 10/11/75 13.0 11/12/75 .05 10/13/75 5.2 11/13/75 .05 10/14/75 2.0 11/14/75 .05 10/15/75 9.9 11/15/75 .05 10/16/75 .58 11/16/75 .06 10/17/75 .36 11/17/75 .06 10/18/75 .19 11/19/75 .06 10/20/75 .18 11/20/75 .04 10/21/75 .16 11/2	10/1/75	8.7	11/1/75	.16	12/1/75	.05
10/4/75 10.0 11/4/75 .07 12/4/75 .0 10/5/75 11.0 11/5/75 .08 10/6/75 11.0 11/6/75 .08 10/7/75 13.0 11/7/75 .07 10/8/75 12.0 11/8/75 .07 10/10/75 12.0 11/10/75 .07 10/11/75 12.0 11/11/75 .06 10/11/75 12.0 11/11/75 .06 10/11/75 12.0 11/11/75 .06 10/11/75 13.0 11/12/75 .05 10/12/75 13.0 11/12/75 .05 10/13/75 5.2 11/13/75 .05 10/14/75 2.0 11/14/75 .05 10/15/75 9.9 11/15/75 .05 10/16/75 .58 11/16/75 .06 10/18/75 .24 11/18/75 .06 10/19/75 .19 11/19/75 .06 10/20/75 .18 11/20/75 .04 10/22/75 .20 11/22/75 .04 <td>10/2/75</td> <td>9.3</td> <td>11/2/75</td> <td>.11</td> <td>12/2/75</td> <td>.04</td>	10/2/75	9.3	11/2/75	.11	12/2/75	.04
10/5/75 11.0 11/5/75 .08 10/6/75 11.0 11/6/75 .08 10/7/75 13.0 11/7/75 .07 10/8/75 12.0 11/8/75 .07 10/9/75 12.0 11/9/75 .07 10/10/75 12.0 11/10/75 .07 10/11/75 12.0 11/11/75 .06 10/12/75 13.0 11/12/75 .05 10/13/75 5.2 11/13/75 .05 10/13/75 5.2 11/13/75 .05 10/14/75 2.0 11/14/75 .05 10/15/75 9.9 11/15/75 .05 10/16/75 .58 11/16/75 .06 10/17/75 .36 11/17/75 .06 10/18/75 .24 11/18/75 .06 10/19/75 .19 11/19/75 .06 10/20/75 .18 11/20/75 .04 10/22/75 .20 11/22/75 .04 10/23/75 .33 11/23/75 .04 10/25/75 <t< td=""><td>10/3/75</td><td>9.9</td><td>11/3/75</td><td>.10</td><td>12/3/75</td><td>.02</td></t<>	10/3/75	9.9	11/3/75	.10	12/3/75	.02
10/6/75 11.0 11/6/75 .08 10/7/75 13.0 11/7/75 .07 10/8/75 12.0 11/8/75 .07 10/9/75 12.0 11/9/75 .07 10/10/75 12.0 11/10/75 .07 10/11/75 12.0 11/11/75 .06 10/12/75 13.0 11/12/75 .05 10/13/75 5.2 11/13/75 .05 10/14/75 2.0 11/14/75 .05 10/15/75 9.9 11/15/75 .05 10/15/75 9.9 11/15/75 .06 10/16/75 .58 11/16/75 .06 10/17/75 .36 11/17/75 .06 10/18/75 .24 11/18/75 .06 10/19/75 .19 11/19/75 .06 10/20/75 .18 11/20/75 .04 10/21/75 .16 11/21/75 .05 10/22/75 .20 11/22/75 .04 10/23/75 .23 11/23/75 .04 10/25/75 <	10/4/75	10.0	11/4/75	.07	12/4/75	.01
10/7/75 13.0 11/7/75 .07 10/8/75 12.0 11/8/75 .07 10/9/75 12.0 11/9/75 .07 10/10/75 12.0 11/10/75 .07 10/11/75 12.0 11/11/75 .06 10/12/75 13.0 11/12/75 .05 10/13/75 5.2 11/13/75 .05 10/13/75 5.2 11/13/75 .05 10/14/75 2.0 11/14/75 .05 10/15/75 9.9 11/15/75 .05 10/16/75 .58 11/16/75 .06 10/17/75 .36 11/17/75 .06 10/18/75 .24 11/18/75 .06 10/19/75 .19 11/19/75 .06 10/20/75 .18 11/20/75 .04 10/21/75 .16 11/21/75 .05 10/22/75 .20 11/22/75 .04 10/23/75 .33 11/23/75 .04 10/24/75 .28 11/24/75 .04 10/25/75	10/5/75	11.0	11/5/75	.08		
10/8/75 12.0 11/8/75 .07 10/9/75 12.0 11/9/75 .07 10/10/75 12.0 11/10/75 .07 10/11/75 12.0 11/11/75 .06 10/12/75 13.0 11/12/75 .05 10/13/75 5.2 11/13/75 .05 10/14/75 2.0 11/14/75 .05 10/15/75 9.9 11/15/75 .05 10/16/75 .58 11/16/75 .06 10/17/75 .36 11/17/75 .06 10/18/75 .24 11/18/75 .06 10/19/75 .19 11/19/75 .06 10/19/75 .19 11/19/75 .06 10/20/75 .18 11/20/75 .04 10/21/75 .16 11/21/75 .05 10/22/75 .20 11/22/75 .04 10/23/75 .23 11/23/75 .04 10/24/75 .28 11/24/75 .04 10/25/75 .23 11/25/75 .04 10/26/75	10/6/75	11.0	11/6/75	.08		
10/9/75 12.0 11/9/75 .07 10/10/75 12.0 11/10/75 .07 10/11/75 12.0 11/11/75 .06 10/12/75 13.0 11/12/75 .05 10/13/75 5.2 11/13/75 .05 10/14/75 2.0 11/14/75 .05 10/15/75 9.9 11/15/75 .05 10/15/75 9.9 11/15/75 .06 10/15/75 .58 11/16/75 .06 10/17/75 .36 11/17/75 .06 10/18/75 .24 11/18/75 .06 10/19/75 .19 11/19/75 .06 10/19/75 .18 11/20/75 .04 10/20/75 .18 11/20/75 .04 10/21/75 .20 11/22/75 .04 10/23/75 .28 11/24/75 .04 10/24/75 .28 11/24/75 .04 10/25/75 .23 11/25/75 .04 10/26/75 .21 11/26/75 .03 10/28/75	10/7/75	13.0	11/7/75	.07		
10/10/75 12.0 11/10/75 .07 10/11/75 12.0 11/11/75 .06 10/12/75 13.0 11/12/75 .05 10/13/75 5.2 11/13/75 .05 10/14/75 2.0 11/14/75 .05 10/15/75 9.9 11/15/75 .05 10/16/75 .58 11/16/75 .06 10/17/75 .36 11/17/75 .06 10/18/75 .24 11/18/75 .06 10/19/75 .19 11/19/75 .06 10/20/75 .18 11/20/75 .04 10/21/75 .16 11/21/75 .05 10/22/75 .20 11/22/75 .04 10/23/75 .33 11/23/75 .04 10/24/75 .28 11/24/75 .04 10/25/75 .23 11/25/75 .04 10/26/75 .21 11/26/75 .03 10/27/75 .26 11/27/75 .04 10/29/75 .26 11/28/75 .05 10/29/75	10/8/75	12.0	11/8/75	.07		
10/11/75 12.0 11/11/75 .06 10/12/75 13.0 11/12/75 .05 10/13/75 5.2 11/13/75 .05 10/14/75 2.0 11/14/75 .05 10/15/75 9.9 11/15/75 .05 10/16/75 .58 11/16/75 .06 10/17/75 .36 11/17/75 .06 10/18/75 .24 11/18/75 .06 10/19/75 .19 11/19/75 .06 10/20/75 .18 11/20/75 .04 10/21/75 .16 11/21/75 .05 10/22/75 .20 11/22/75 .04 10/23/75 .33 11/23/75 .04 10/24/75 .28 11/24/75 .04 10/25/75 .23 11/25/75 .04 10/26/75 .21 11/26/75 .03 10/27/75 .26 11/27/75 .04 10/28/75 .26 11/28/75 .05 10/29/75 .22 11/29/75 .06 10/30/75	10/9/75	12.0	11/9/75	.07		
10/12/75 13.0 11/12/75 .05 10/13/75 5.2 11/13/75 .05 10/14/75 2.0 11/14/75 .05 10/15/75 9.9 11/15/75 .05 10/16/75 .58 11/16/75 .06 10/17/75 .36 11/17/75 .06 10/18/75 .24 11/18/75 .06 10/19/75 .19 11/19/75 .06 10/20/75 .18 11/20/75 .04 10/21/75 .16 11/21/75 .05 10/22/75 .20 11/22/75 .04 10/23/75 .33 11/23/75 .04 10/23/75 .28 11/24/75 .04 10/25/75 .23 11/25/75 .04 10/25/75 .23 11/25/75 .04 10/26/75 .21 11/26/75 .03 10/27/75 .26 11/27/75 .04 10/28/75 .26 11/28/75 .05 10/29/75 .22 11/29/75 .06 10/30/75	10/10/75	12.0	11/10/75	.07		
10/13/75 5.2 11/13/75 .05 10/14/75 2.0 11/14/75 .05 10/15/75 9.9 11/15/75 .05 10/16/75 .58 11/16/75 .06 10/17/75 .36 11/17/75 .06 10/18/75 .24 11/18/75 .06 10/19/75 .19 11/19/75 .06 10/20/75 .18 11/20/75 .04 10/21/75 .16 11/21/75 .05 10/22/75 .20 11/22/75 .04 10/23/75 .33 11/23/75 .04 10/24/75 .28 11/24/75 .04 10/25/75 .23 11/25/75 .04 10/26/75 .21 11/26/75 .03 10/27/75 .26 11/27/75 .04 10/28/75 .26 11/28/75 .05 10/29/75 .22 11/29/75 .06 10/30/75 .21 11/30/75 .05	10/11/75	12.0		.06		
10/13/75 5.2 11/13/75 .05 10/14/75 2.0 11/14/75 .05 10/15/75 9.9 11/15/75 .05 10/16/75 .58 11/16/75 .06 10/17/75 .36 11/17/75 .06 10/18/75 .24 11/18/75 .06 10/19/75 .19 11/19/75 .06 10/20/75 .18 11/20/75 .04 10/21/75 .16 11/21/75 .05 10/22/75 .20 11/22/75 .04 10/23/75 .23 11/23/75 .04 10/24/75 .28 11/24/75 .04 10/25/75 .23 11/25/75 .04 10/26/75 .23 11/26/75 .03 10/27/75 .26 11/27/75 .04 10/28/75 .26 11/28/75 .05 10/29/75 .22 11/29/75 .06 10/30/75 .21 11/30/75 .05	10/12/75	13.0	11/12/75	.05		
10/14/75 2.0 11/14/75 .05 10/15/75 9.9 11/15/75 .05 10/16/75 .58 11/16/75 .06 10/17/75 .36 11/17/75 .06 10/18/75 .24 11/18/75 .06 10/19/75 .19 11/19/75 .06 10/20/75 .18 11/20/75 .04 10/21/75 .16 11/21/75 .05 10/22/75 .20 11/22/75 .04 10/23/75 .33 11/23/75 .04 10/24/75 .28 11/24/75 .04 10/25/75 .23 11/25/75 .04 10/26/75 .21 11/26/75 .03 10/27/75 .26 11/27/75 .04 10/28/75 .26 11/28/75 .05 10/29/75 .22 11/29/75 .06 10/30/75 .21 11/30/75 .05	10/13/75	5.2		.05		
10/16/75 .58 11/16/75 .06 10/17/75 .36 11/17/75 .06 10/18/75 .24 11/18/75 .06 10/19/75 .19 11/19/75 .06 10/20/75 .18 11/20/75 .04 10/21/75 .16 11/21/75 .05 10/22/75 .20 11/22/75 .04 10/23/75 .33 11/23/75 .04 10/23/75 .28 11/24/75 .04 10/24/75 .28 11/24/75 .04 10/25/75 .23 11/25/75 .04 10/26/75 .21 11/26/75 .03 10/27/75 .26 11/27/75 .04 10/28/75 .26 11/28/75 .05 10/29/75 .22 11/29/75 .06 10/30/75 .21 11/30/75 .05	10/14/75	2.0		.05		
10/17/75 .36 11/17/75 .06 10/18/75 .24 11/18/75 .06 10/19/75 .19 11/19/75 .06 10/20/75 .18 11/20/75 .04 10/21/75 .16 11/21/75 .05 10/22/75 .20 11/22/75 .04 10/23/75 .33 11/23/75 .04 10/24/75 .28 11/24/75 .04 10/25/75 .23 11/25/75 .04 10/25/75 .23 11/25/75 .04 10/26/75 .21 11/26/75 .03 10/27/75 .26 11/27/75 .04 10/28/75 .26 11/28/75 .05 10/29/75 .22 11/29/75 .06 10/30/75 .21 11/30/75 .05	10/15/75	9.9	11/15/75	.05		
10/18/75 .24 11/18/75 .06 10/19/75 .19 11/19/75 .06 10/20/75 .18 11/20/75 .04 10/21/75 .16 11/21/75 .05 10/22/75 .20 11/22/75 .04 10/23/75 .33 11/23/75 .04 10/23/75 .28 11/24/75 .04 10/25/75 .23 11/25/75 .04 10/26/75 .23 11/26/75 .03 10/26/75 .21 11/26/75 .03 10/27/75 .26 11/27/75 .04 10/28/75 .26 11/28/75 .05 10/29/75 .22 11/29/75 .06 10/30/75 .21 11/30/75 .05	10/16/75	.58		.06		·
10/19/75 .19 11/19/75 .06 10/20/75 .18 11/20/75 .04 10/21/75 .16 11/21/75 .05 10/22/75 .20 11/22/75 .04 10/23/75 .33 11/23/75 .04 10/24/75 .28 11/24/75 .04 10/25/75 .23 11/25/75 .04 10/26/75 .21 11/26/75 .03 10/27/75 .26 11/27/75 .04 10/28/75 .26 11/28/75 .05 10/29/75 .22 11/29/75 .06 10/30/75 .21 11/30/75 .05	10/17/75	.36	11/17/75	.06		
10/20/75 .18 11/20/75 .04 10/21/75 .16 11/21/75 .05 10/22/75 .20 11/22/75 .04 10/23/75 .33 11/23/75 .04 10/24/75 .28 11/24/75 .04 10/25/75 .23 11/25/75 .04 10/26/75 .21 11/26/75 .03 10/27/75 .26 11/27/75 .04 10/28/75 .26 11/28/75 .05 10/29/75 .22 11/29/75 .06 10/30/75 .21 11/30/75 .05	10/18/75	. 24	11/18/75	.06		
10/20/75 .18 11/20/75 .04 10/21/75 .16 11/21/75 .05 10/22/75 .20 11/22/75 .04 10/23/75 .33 11/23/75 .04 10/24/75 .28 11/24/75 .04 10/25/75 .23 11/25/75 .04 10/26/75 .21 11/26/75 .03 10/27/75 .26 11/27/75 .04 10/28/75 .26 11/28/75 .05 10/29/75 .22 11/29/75 .06 10/30/75 .21 11/30/75 .05	10/19/75	.19	11/19/75	.06		
10/22/75 .20 11/22/75 .04 10/23/75 .33 11/23/75 .04 10/24/75 .28 11/24/75 .04 10/25/75 .23 11/25/75 .04 10/26/75 .21 11/26/75 .03 10/27/75 .26 11/27/75 .04 10/28/75 .26 11/28/75 .05 10/29/75 .22 11/29/75 .06 10/30/75 .21 11/30/75 .05	10/20/75	.18		.04		
10/22/75 .20 11/22/75 .04 10/23/75 .33 11/23/75 .04 10/24/75 .28 11/24/75 .04 10/25/75 .23 11/25/75 .04 10/26/75 .21 11/26/75 .03 10/27/75 .26 11/27/75 .04 10/28/75 .26 11/28/75 .05 10/29/75 .22 11/29/75 .06 10/30/75 .21 11/30/75 .05	10/21/75	.16	11/21/75	.05		
10/24/75 .28 11/24/75 .04 10/25/75 .23 11/25/75 .04 10/26/75 .21 11/26/75 .03 10/27/75 .26 11/27/75 .04 10/28/75 .26 11/28/75 .05 10/29/75 .22 11/29/75 .06 10/30/75 .21 11/30/75 .05	10/22/75	.20	11/22/75	.04		
10/25/75 .23 11/25/75 .04 10/26/75 .21 11/26/75 .03 10/27/75 .26 11/27/75 .04 10/28/75 .26 11/28/75 .05 10/29/75 .22 11/29/75 .06 10/30/75 .21 11/30/75 .05	10/23/75	.33	11/23/75	.04		
10/26/75 .21 11/26/75 .03 10/27/75 .26 11/27/75 .04 10/28/75 .26 11/28/75 .05 10/29/75 .22 11/29/75 .06 10/30/75 .21 11/30/75 .05	10/24/75	.28		.04		
10/27/75 .26 11/27/75 .04 10/28/75 .26 11/28/75 .05 10/29/75 .22 11/29/75 .06 10/30/75 .21 11/30/75 .05	10/25/75	.23	11/25/75	.04		
10/28/75 .26 11/28/75 .05 10/29/75 .22 11/29/75 .06 10/30/75 .21 11/30/75 .05	10/26/75	.21	11/26/75	.03		
10/29/75 .22 11/29/75 .06 10/30/75 .21 11/30/75 .05	10/27/75	.26	11/27/75	.04		
10/30/75 .21 11/30/75 .05	10/28/75	.26	11/28/75	.05		
, · ·	10/29/75	.22	11/29/75	.06		
10/31/75 .19	10/30/75	.21	11/30/75	.05		
	10/31/75	.19	•			
Total 155.10 1.86 .1	Total	155.10		1.86		.12

LOWER GAUGE

3/1/76		4/1/76	3.70
3/2/76		4/2/76	3.20
3/3/76		4/3/76	3.70
3/4/76		4/4/76	3.00
3/5/76		4/5/76	4.90
3/6/76		4/6/76	5.10
3/7/76		4/7/76	4.80
3/8/76	.27	4/8/76	4.70
3/9/76	.35	4/9/76	3.90
3/10/76	.45	4/10/76	3.10
3/11/76	.60	4/11/76	2.70
3/12/76	.50	4/12/76	2.40
3/13/76	.70	4/13/76	2.00
3/14/76	.68	4/14/76	1.90
3/15/76	.65	4/15/76	2.90
3/16/76	1.00	4/16/76	3.50
3/17/76	1.50	4/17/76	2.70
3/18/76	2.50	4/18/76	2.10
3/19/76	2.40	4/19/76	1.80
3/20/76	2.20	4/20/76	1.60
3/21/76	3.00	4/21/76	1.50
3/22/76	4.00	4/22/76	1.30
3/23/76	4.50	4/23/76	1.30
3/24/76	5.20	4/24/76	1.00
3/25/76	5.90	4/25/76	1.10
3/26/76	5.20	4/26/76	2.00
3/27/76	4.90	4/27/76	1.90
3/28/76	4.60	4/28/76	1.60
3/29/76	4.30	4/29/76	1.30
3/30/76	4.00	4/30/76	1.10
3/31/76	3.70		
Total	63.10		77.80

LOWER GAUGE

5/1/76	. 94	6/1/76	.11	7/1/76	.02
5/2/76	.81	6/2/76	.09		
5/3/76	.74	6/3/76	.08		
5/4/76	.62	6/4/76	.07		
5/5/76	. 58	6/5/76	.06		
5/6/76	.70	6/6/76	.06		
5/7/76	.82	6/7/76	.06		
5/8/76	.91	6/8/76	.06		
5/9/76	1.10	6/9/76	.05		
5/10/76	.89	6/10/76	.03	· ·	
5/11/76	.67	6/11/76	.05		
5/12/76	.49	6/12/76	.09		
5/13/76	.38	6/13/76			
5/14/76	.23	6/14/76	.25		
5/15/76	.28	6/15/76	.19		
5/16/76	. 27	6/16/76	.12		
5/17/76	.25	6/17/76	.12		
5/18/76	.22	6/18/76	.13		
5/19/76	.21	6/19/76	.11		
5/20/76	.21	6/20/76	.07		
5/21/76	.29	6/21/76	.04		
5/22/76		6/22/76	.04		
5/23/76	.33	6/23/76	.08		
5/24/76	.43	6/24/76	.08		
5/25/76	.28	6/25/76	.06		
5/26/76	.23	6/26/76	.03		
5/27/76	.19	6/27/76	.01		
5/28/76	.17				
5/29/76	.15	÷			
5/30/76	.14				
5/31/76	.13	• .		•	
Total	13.66		2.14		.02

TOTAL LOWER GAUGE 313.80